DRAWING NOTES - GENERAL:

- DO NOT ALTER THIS DRAWING.
- THIS IS A REFERENCE DRAWING ONLY.
- SEE SolidWorks FILE FOR DETAILS
- IF IN DOUBT ASK.

FABRICATED PARTS:

- REMOVE ALL BURRS AND SHARP EDGES.
- CLEAN AND FULLY DEGREASE.
- ALL WELDS TO BE DRESSED FLUSH.
- BLANK DRAWING -
  K FACTOR = 0.5, INSIDE BEND RADIUS = 1 X GAUGE







THIS IS A CAD DRAWING & MUST NOT BE ALTERED MANUALLY

3RD ANGLE PROJECTION

ISSUE HISTORY ONLY - SEE TITLE BOX FOR LATEST ISSUE

ISSUE:	DATE:	CHANGE:
-	00.00.0000	-



ISOMETRIC VIEW

LATEST ISSUE

ISSUE:	DATE:	DESCRIPTION:
A	01/06/2008	Prototype Only

CHANGE:
-

MATERIAL: To be agreed
FINISH: To be agreed

PLASTECH Ltd.
Unit 4, Ricebridge Works,Brighton Road
Bolney, West Sussex, England - RH17 5NA
TEL: 01444 881960 FAX: 01444 881244
E-MAIL: mark@plastch.com
WEB: www.plastch.com

THIS DRAWING MUST NOT BE USED FOR MANUFACTURE UNLESS SPECIFICALLY STATED.

THIS DRAWING IS CONFIDENTIAL AND MUST NOT BE COPIED OR DISCLOSED WITHOUT PRIOR WRITTEN CONSENT.

Tolerances:

Whole numbers ± 0.4
1 decimal place ± 0.2
2 decimal places ±0.05

Angles ± 1°
Unless Stated

DIMENSIONS IN mm

DRAWN: NDR
CHECKED: -
SCALE: 5:1@A3
DATE: 01/06/2008
PROJECT No. RA 1059

TITLE: Tap Off Fuse Clip
PART REFERENCE. ZUF0301
Client DWG No. SK4583
RA DWG No. RA 1059-044_PT
SHEET No. 1 of 1
A3

0 10 20 30 40 50 100mm
RA A3 L Link